Umetco Minerals Corporation



PO BOX 66 137 47th STREET • NIAGARA FALLS NEW YORK 14302

November 26, 1986

Mr. C. T. Wentzel
U. S. Vanadium Corporation
P. O. Box 66
Niagara Falls, NY 14302

Subject Disposal of Sample Cans

Dear Craig

The last of the metallurgical samples stored in the Globar area that dated back as far as 1902 were removed from the Niagara Plant on November 24, 1986 by SCA Chemical Services. A copy of the Hazardous Waste Manifest is appended. An earlier shipment of non-hazardous samples were removed by BFI Waste Systems on October 10, 1986 (manifest appended). Radioactive samples were included in a shipment to Barnwell Waste Management Facility, South Carolina September 19, 1986.

On Wednesday, November 26, 1986, Al Gonas and I accompanied Mr. Herb Wilber to inspect the area in Globar where the samples has been stored. A radioactive survey was made at that time to confirm that no traces of the radioactive samples had been left on the shelves or in the storage containers. A copy of the letter from Herb Wilber to you attesting to the satisfactory completion of the sample cans removal is also appended.

This completes the obligation of Umetco Minerals to Stratcor Minerals Corporation as outlined in Item 3 (g) of the Environmental Agreement (Niagara Falls) between Umetco Minerals Corporation and U. S. Vanadium Corporation which reads:

"(g) <u>Sample Cans</u> Umetco further agrees to assume the cost of removal and disposal of the numerous small sample cans in the globar area."

Page 2 November 26, 1986

Would you and Dr. Miller, as members of the Stratcor Environmental Coordination Committee for the Niagara Plant, acknowledge acceptance by signing the second copy of this letter and returning it to me.

Very truly yours,

,			
ACCEPTED BY:			
U. S. VANADIUM			
By:			
Title:			
By:			
Title:			
cc: Messrs: W. G. Beattie J. F. Frost T. J. Kagetsu F. V. McMillen D. G. Millenbruch			

R. L. Miller

In case of emergency or apili immediately call the National Response Center (800) 424-8802 and the N.Y Department of Transportation (618) 457-7362.

DEPARTMENT OF ENVIRONMENTAL CONSERVATION DIVISION OF SOLID AND HAZARDOUS WASTE

P.O Box 12820, Albany, New York 12212

	UNIFORM HAZARDOUS 1 Generator's US EPA No Manifest Document No Is not required by Federal Law WASTE MANIFEST 1 Generator's US EPA No Manifest Document No Is not required by Federal Law		
	3 Generator's Name and Mailing Address UMETCO MINERALS CORP A State Handle Document Ra		
	4 Generator's Phone (7/6) 286-4028 NIABARA FALLS, N.Y		
}	5 Transporter 1 (Company Name) 6 US EPA ID Number CISTA STEPANDED 1 1 D D D S D B D B D S PANDED 1 Transporter 2 (Company Name) 8 US EPA ID Number E S D Transporter 2 (Company Name) 8 US EPA ID Number E S D Transporter 2 (Company Name)		
	The state of the s		
	SCA CHEMICAL SERVICES 1550 BALMER AB		
*	MODEL CITY, N-Y. 14107 WYD 04 983 6674		
	11 US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number) Total Unit WitVol February Ouantity WitVol		
GENER	NA 9189 010 0M 9000 P		
Ā	· HAMEDING WAITE SUIS MES, OCH !!		
R	NA 9189 1800 P		
	C Barrier and Annual Courts an		
	Additional Descriptions for platential stated Places To The Addition Codes for The States Listed Addition Codes for The St		
	15 Special Handling Instructions and Additional Information a.) (40770 d)		
	b. (6017) the drawn as a sulf marries is		
,	GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government		
	Explain the first state taws and state taws are regulations. Unless! am a small quantity generator who has been exempted by statute or regulation from the duty to make a waste minimization certification under Section 3002 (b) of RCRA, I also certify that! have a program in place to reduce volume and toxicity of waste generated to the degree! have determined to be economically practicable and I have selected the method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment		
:	Printed/Typed Name Albert M Gowas Signature		
TRA	17. Transporter 1 (Acknowledgement of Receipt of Materials) Printed/Typed Name Mo Day Year		
20 P O	18. Transporter 2 (Acknowledgement or Receipt of Materials)		
ATER	RintedTyped Name The Control of the		
FAC	אין אין מיין אין אין אין אין אין אין אין אין אין		
20 Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in item 19			
Y	Printed/Typed Name Signature Signatu		

EPA Form 8700-22 (Rev. 4-85) Previous edition is obsolete. Copy 8—Generator—retained by generator

INSTRUCTIONS FOR THE UNIFORM HAZARDOUS WASTE MANIFEST

New York State regulation requires proper completion of all information on a manifest. Omissions, false coding or illegibility is considered a violation. All gr erators are responsible under New York State and Federal Law for the proper identification. labeling, manifesting and ultimate disposal of all hazardous was a they generate. The manifest system is designed to track hazardous waste from the point of generation until its final disposal (cradle to grave). In order, to accomplish this goal it is essential that all items on a manifest be properly completed

Distribution

Distribution of each copy of the manifest is indicated on the bottom of the form. Copies of the manifest must be mailed promptly. New York State regulations provide five (5) working days for generator and two (2) for a TSDF. The Disposer's state is the state in which the designated TSD facility is located. Generator is state is the state in which the installation generating the hazardous waste is located. TSD facility is a treatment, storage or disposal facility

Generator Section

Item 1 Enter the US EPA ID number (twelve dig - number issued by the federal government). The generator must assign a sequential unique, five digit number different for each manifest as the manifest number

Item 2 If a continuation sheet is used please enter the total number of sheets here. Any EPA approved continuation sheet may be used, but distribution and completion must meet New York manifest requirements. The document number in Item A must be placed in Item L of each continuation sheet

Item 3 and 4-Self Explanatory These must correspond to the generators US EPA ID number

Items 5, 6, 7 and 8 These are self explanatory. These numbers must be secured from the transporter. If more than one transporter is used, the generator must supply additional copies of this manifest (copy#5) for each transporter

Items 9 and 10 The designated TSD facility, name, address and ID number should appear here

NOTE. All US EPA ID numbers are a twelve digit code starting off with the letters corresponding to the state in which the facility or transporter is located

NOTE. Only New York State authorized transporters and TSD facilities are allowed to transport or receive hazardous waste in New York State. The generator shall check for authorization

Item 11 USDOT requires the word waste before or in the shipping name for all hazardous waste. See 49 CFR 171 thru 173. Contact USDOT office for description assistance. Any waste in this box is considered a hazardous waste

Number-indicate number of containers (use whole numbers)

Containers/Type ,

DM Metal drums barrels

TT Cargo tank tank trucks DT Dump trucks

CY Cylinders

DW Wooden drums barrels.

TP Tanks, portable

CM Metal boxes, cases, roll offs

CW Wooden boxes

-DF Fiberboard or plastic drums (glass)

FC-Tank cars

CF Fiber or plastic boxes cartons BA Burlap plastic paper bags

Item 13-Actual number of units indicated in box 14 (Do not use fractions or decimals)

item 14-Units (wt/vol)

G Gallons (liquids only) [8 3 pounds] L Liters (liquid only) [2.2 pounds]

N Cubic meters* [2,200 pounds]

P Pounds Tions

K Kilograms [2.2 pounds]

M Metric tons (1 000 kilograms) [2 200 pounds]

Item 15-Use this space to indicate special transportation, treatment, storage or disposal or Bill of Lading information. If an alternate facility is designated, note It here For international shipments, enter point of departure. Emergency response telephone numbers, or similar information may be included here

Item 16-The authorized agent of the generator must read and then sign (by hand) and date this certification. The date is the date of receipt by transporter

NEW YORK STATE REQUIRES THIS ADDITIONAL INFORMATION

Item A Number preprinted by New York State Department of Environmental Conservation (NYSDEC)

Item B Generator site address if different from mailing address. If same, write in same

Item C and E State of registration and motor vehicle license plate number of waste carrying portion of vehicle used to transport

Item D and F Telephone number of authorized agent

Item G No entry required by NYSDEC

Item H Telephone number at site of TSD facility

Item I Hazardous waste numbers (letter and three digits) as assigned by Part 356/371 (40 CFR 261 subparts C and D) must be used to identify hazardous waste If waste is not hazardous in New York but regulated by another state, enter that state's waste code

Item J If description in item 11 (a bid d) contains NOS or other general term, the hazardous waste constituent must be provided here for each. The specific gravity assumed to be one (1 00) unless indicated in lower right of each box

Item K Each material must be assigned an ultimate disposal method code as follows L = landfill B = incineration heat recovery burning T = Chemical physical or biological treatment R = Material recovery of more than 75 percent of the total material. Both the generator and the TSDF should agree on codes assigned in this item

Items 17 and 18 Print or type trie full name of person accepting responsibility and acknowledging receipt of material as listed on manifest for transport. Enter date of receipt and signature

Item 19 The authorized representative of the TSDF must note in the space any discrepancy between waste described on manifest and waste actually received Any rejected materials should be listed and destination of those materials provided

Item 20 The signature (by hand) of the authorized TSDF agent indicates acceptance (except for Item 19) and agreement with statements on this manifest. The date is the date of signature and receipt of shipment. A TSDF not providing ultimate disposal agrees to transfer waste to a TSDF authorized to provide ultimate disposal as indicated in Item K

- 1 If the Disposer State supplies a manifest, that state's form must be used. In any case, New York requires that both the generator and TSDF mail conies to the generator's State and the disposer's State with the ultimate disposal method indicated in Item K
- 2. There may be variations in the requirements between various states regarding items A thru K, therefore, the generator should contact the dispose is Sid 6.
- 3 It assistance is needed in completion of this manifest, please contact NYSDEC Manifest Section at 518/457-0530 weekdays from 9.00 a.m. to 4.00 p.m.

Y Cubic yards [85 tons] *Specify gravity 1 00 unless indicated in box J

	WORK ORDER
SCA CHEMICAL SERVICES, INC.	DATE
P.O Box 200, 1550 Balmer Road	
Model City, New York 14107	TRACTOR
A FIGRATICAL STATE OF THE STATE	
NAME	DEIVERY
C AMOUNT OF A CASE OF THE COLUMN	SCA Character Son Kiths
H STATE TO THE TOTAL STATE OF THE STATE OF T	N STREET
CITY STATE ZIP CODE	S CITY STATE ZIP CODE
LI AMERICA STATE WITH THE	11 Mars Adams to 1
CONTACT NAME	G CONTACT NAME
R SCHEDULED TIME	E SCHEDULED TIME
	E
ADDITIONAL INFORMATION	ADDITIONAL INFORMATION
	, sea " -
The second secon	
PRODUCT CODE MATERIAL DESCRIPTION	QUANTITY GROSS SHIPPERS RECOMMENDED
CODIN COLOM SUCCO	TARE PLACARD (CIRCLE)
001100 11100	NON-FLAMMABLE
(601%03) PIC-	San NET FLAMMABLE
	SOUD UNDUID
	CORROSIVE
	FLAMMABILITY
	DRIVE SAFELY
• • • • • • • • • • • • • • • • • • • •	HEALTH REACTIVITY
	PCB.
A second	WATER
	DANGEROUS
	OTHER
PICK UP	DELIVERY
	DRIVER DATE
ARRIVAL TIME MRELEASE TIME	AM
TO AN CO FACTIVILIDON A DONAL	ARRIVAL TIME PM RELEASE TIME PM
TRAILER EMPTY UPON ARRIVAL If not, explain below) WES NO	TRAILER EMPTY UPON DEPARTURE
DIP MEASUREMENT (Tankers Only)	## not explain below)
	COMMENTS (EXPLAIN ALL DELAYS)
	COMMENTS (EXPLAIN ALL DECAYS)
	A STATE OF THE STA
1. THE UNDERSIGNED, CERTIFY THAT THE ABOVE INFORMATION IS. TRUE AND COMPLETE.	I I THE UNDERSIGNED, CERTIFY THAT THE ABOVE INFORMATION IS
	TRUE AND COMPLETE.
DRIVER'S SIGNATUR	
	DRIVER'S SERVICIANE
SHAPER'S SIGNATURE	CONSIGNETS, SIGNATURE



NON-HAZARDOUS WASTE MANIFEST

Full surfle Come Dex Broken

ENER L	RATOR
Generator Name (MITEL PROJECT)	Shipping Location Limited Mindfilling
Address 10. Box 1129	Address 47 Th FROUNT
Grand Junition (10 81	52 NUGERA 1. 115 M
Phone No	Phone No 7/6-27832/4
BFI Lab Number Description of Waste	Quantity Units No Type D - Drum
26661 NON 1112. CORE 59	MES SUY HE C-Carton B-Bag
	T- Truck P - Pounds Y - Yards
	O - Other
state law, is not a hazardous waste as defined by 40 CFR Par classified and packaged, and is in proper condition for transport	n free liquid as defined by 40 CFR Part 260 10 or any applicable t 261 or any applicable state law, has been properly described, relation according to applicable regulations
General Administration of the Company of the Compan	Shipment Date
TRANS	PORTER
Transporter Name Almerica SANTATION IM	Driver Name (Print) Authory G B + K
Address YO Kur 57/	Vehicle License No /State 434/1 GK V. X
KINIMORE UT 14172	Vehicle Certification 9A065
I hereby certify that the above named material was picked up at the generator site listed above	I hereby certify that the above named material was delivered without incident to the destination listed below
Driver Signature Shipment Pate	Driver Signature Delivery Date
	Driver Signature Delivery Date
ad ≣ Stí	NATION STATE OF STATE
Site Name ACARO LAJOFHI NC.	Phone No 7/6-2828692
Site Name ACAPO LAJDÍH NC Address Lini Coul I hereby certify that the above named material has been accepted a	Phone No 7/6-2828672 And to the best of my knowledge the foregoing is true and accurate
Site Name ACAPO LOJDÍJI NC. Address School Coul Jim	Phone No 7/6-2878692

BF1260 729

WORK ORDER NO. 11/409

Landburial Ban WASTE CERTIFICATION FORM CWM-WASTE CODE: G07707

(To be attached to the Manifest Form for first time shipments, annually, when the waste stream composition changes, or when otherwise required by NYSDEC)

Part A (General)

1. Describe the process producing the waste (including the representative SIC coce).

MANUFACTURING OF METAL ALLOYS METAL ORES

2. Is this material a "one time" shipment or a continuing ONE THATE waste stream? 3. Is this material from an inactive hazardous waste NO site or spill cleanup? 4. a. Does this waste contain organic chemicals? b. If so, does this waste contain: 1. aromatics? 2. halogenated organics? 3. nitrogenated organics? 4. low molecular weight organics? 5. Does this stream contain any organic materials listed in 6NYCRR 366.4(d)(5) and 366.4(d)(6) (P-list or NO U-list)? If so, list them:

If any of the answers to question 4 or 5 were yes or unknown, complete Part B of this certification for those classes of materials which are known or suspected to be in the waste. If you answered no to all of these questions; please sign the following certification:

BASED ON MY KNOWLEDGE OF THE PROCESS AND CHEMICALS USED IN GENERATING THE WASTE, I CERTIFY THAT-THESE WASTES QUALIFY FOR LANDBURIAL UNDER THE NEW YORK STATE LANDBURIAL BAN AS DESCRIBED ON THIS FORM. I FURTHER CERTIFY THAT I WILL RESUBMIT THIS FORM IF THE WASTE STREAM COMPOSITION CHANGES IN A WAY WHICH MIGHT INCREASE THE CONCENTRATIONS OF ORGANIC CHEMICALS IN THE WASTE STREAM.

IT IS A CRIME, PUNISHABLE AS A CLASS A MISDEMEANOR UNDER THE LAWS OF THE STATE OF NEW YORK, FOR A PERSON, IN AND BY A WRITTEN INSTRUMENT, TO KNOWINGLY MAKE A FALSE STATEMENT, OR TO MAKE A STATEMENT WHICH SUCH PERSON DOES NOT BELIEVE TO BE TRUE.

Signature: <u>Allet M. In</u>

Date: <u>4/25/86</u> Name: Title:

Umatro Minerals Corp

Nigsara Folls MY

P. O. Box 66 Niagara Falls, NY 14302

November 26, 1986

TO:

C. T. Wentzel

COPY:

D. J. Hansen

SUBJECT:

Sample Cage

The sample cage is clean and all samples have been removed. This area is also clean of radioactivity. Numerous sample jars have been left for J. Cooper. These jars are physically clean, but haven't been rinsed. As far as I'm concerned, Umetco has fulfilled their clean-up requirements.

7/m Wilber

HMW:1p